

## UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 4
ATLANTA FEDERAL CENTER
61 FORSYTH STREET
ATLANTA, GA 30303-8960

August 15, 2003

4WD/FFB

Commanding Officer
Attn: Jim Reed
Code 1872
SOUTHNAVFACENGCOM
2155 Eagle Drive
North Charleston, South Carolina 29419-9010

Subject: Corrective Measures Study Report, SWMU 39, Revision: 1, Naval Support Activity Mid-South, Millington, Tennessee

Dear Mr. Reed,

EPA has reviewed the subject report. The selected remedy Monitored Natural Attenuation is appropriate given the contaminant concentrations and hydrogeology at SWMU 39. However, the estimated time frame for groundwater to reach MCLs is excessive and could be accelerated with passive injection as discussed in the August 6, 2003 BCT teleconference call. Enhanced in-situ bioremediation along with monitored natural attenuation is the optimal remedy for groundwater remedation at SWMU 39.

If you have any questions please contact me at 404-562-8513.

Sincerely,

Jennifer Tufts

Remedial Project Manager

cc:

Rob Williamson, Public Works Office Roger Donovan, TDEC - Nashville John Stedman, Ensafe - TOM Jack Carmichael, USGS